

Download 1992 Mr2 Engine 02 Sensor Replacement Guide

Toyota adverts - all ads for modern Toyota cars shown in one place together Using universal performance parts helps take the hassle out of selecting parts for tuner car projects. Order the performance parts you need today! The Toyota Mark II (Japanese: マークII, Toyota M?ku II) is a mid-size sedan manufactured and marketed in Japan by Toyota between 1968 and 2004. Prior to 1984, the model was marketed as the Toyota Corona Mark II. In some export markets, Toyota marketed the vehicle as the Toyota Cressida between 1976 and 1992 across four generations. Toyota replaced the Cressida in North America ... Reconnect air bag sensor assembly connector A21 to air bag sensor assembly. Connect negative battery cable. Wait at least 2 seconds. Turn ignition switch to ON position. Wait at least 20 seconds. Clear DTCs. See CLEARING CODES under DIAGNOSTICS.